

Technical Bulletin

Bulletin No.: PRO-GI-04 Effective Date: 7/15/83 Cancels: N/A Page: 1 of 1

Subject: Elimination of Tapped Screw Holes in Replacement Parts

Note: This bulletin cancels bulletin PRO-GI-4 Dated 8/16/82

This is to announce that device body, inter-body and cover castings with untapped screw holes will NO LONGER BE AVAILABLE AS SERVICE REPLACEMENTS.

The following valve bodies will no longer be available as service parts. This is an on-going program that will affect additional components in the future.

1. R-6, R-8, R-8P, R-12 & R-14 Relay Valves
2. RE-6 Relay Emergency Valve
3. E-6, E-7, E-10 Brake Valves
4. TC-2 Trailer Control Valve
5. QR-1 Quick Release Valve
6. SR-1 Spring Brake Valve

AD-2 and AD-3 end covers will be supplied with threaded retainer clip holes under the same piece numbers as in the past.

